



"Christopher Warner"
<clwarner@gw.dec.state.ny.us>

02/04/2010 01:32 PM

To Frank Billingsley/R2/USEPA/US@EPA

cc

bcc

Subject Re: ~~Titus~~ **TITAN** Express/ Binghamton

Frank,

#1. Evidence of leaking tanks were product in the interstitial space of the tanks, stained soils. sheen on the groundwater and test results on soil samples showing petroleum contamination.

#2. No soils stockpiled. Soil is being hauled directly to the landfill upon excavating due to lack of room on the site.

#3 We have photos of the contamination along with test results.

#4 The contractor has been onsite continuously from January 22, 2010 to present.

Chris

Ps.. The site name is TITAN Express not Titus.

Christopher L. Warner
Environmental Engineering Technician 3
NYSDEC Region 7 -- Kirkwood
1679 NY Rt. 11
Kirkwood, New York 13795

607-775-2545 XT. 119
607-775-2019 (Fax)

>>> <Billingsley.Frank@epamail.epa.gov> 2/4/2010 1:09 PM >>>

Good afternoon Chris.

It was á pleasure to meet you at the site yesterday.

As I mentioned Wednesday below are questions. Please get back to me tomorrow with answers by email.

- 1) What was the evidence of leaking tanks at the site?
- 2) Were there any soils stockpiled?
- 3) What information documented contamination?
- 4) What are the dated the contractor has been out at site working?

Appreciate it.